# Saddle Tramp
## MOTORCYCLE ACCESSORIES

Prior to installing the Saddle Tramp BC-DSP, it is important to update the factory radio. The steps outlined below will demonstrate how to update, using a Windows PC.

NOTE: DSP Harness must not be connected when updating the OEM radio

**Updating the factory installed radio:**

- Click/copy this link **tiny.cc/6z0fvz**
- Select the Radio type

**Updating the factory installed radio:**

- Select the region the vehicle was originally sold in

- In this example we're using North America
  NOTE: If you have a 6.5GT radio, please note the CVO variant

### BOOM! BOX 4.3 Standard Radio

Table 7. BOOM! BOX 4.3

| SOFTWARE AND APPLICATION | LATEST VERSION | SOFTWARE FILE LOCATION | HARDWARE PART NUMBER | OWNER'S MANUAL |
|---|---|---|---|---|
| BOOM! BOX 4.3 Standard - North America | 1.22.0.1 | BOOM_4.3_Standard Radio - North America | 76000075 | Latest BOOM! BOX 4.3 Owner's Manual |
| BOOM! BOX 4.3 Standard - International | 1.22.0.1 | BOOM_4.3 Standard Radio – International | 76000230 | |

### BOOM! BOX 6.5GT

Table 5.

| SOFTWARE AND APPLICATION | LATEST VERSION | SOFTWARE FILE LOCATION | HARDWARE PART NUMBER | OWNER'S MANUAL |
|---|---|---|---|---|
| BOOM! BOX 6.5GT Premium Radio - North America | 1.22.0.3 | GEN1_BOOM_6.5GT Premium Radio - North America | 76000076 | 2018 BOOM! BOX Owner's Manual |
| BOOM! BOX 6.5GT Premium Radio - Europe | 1.22.0.3 | GEN1_BOOM_6.5GT Premium Radio - Europe | 76000231 | |
| BOOM! BOX 6.5GT Premium Radio - International | 1.22.0.3 | GEN1_BOOM_6.5GT Premium Radio - International | 76000232 | |
| BOOM! BOX 6.5GT CVO Premium Radio - North America | 1.22.0.3 | GEN1_BOOM!_BOX_6.5GT CVO Premium Radio - North America | 76000228 | |
| BOOM! BOX 6.5GT CVO Premium Radio - Europe | 1.22.0.3 | GEN1_BOOM!_BOX_6.5GT CVO Premium Radio - Europe | 76000229 | |

### BOOM! BOX Audio

#### 2019 and Later BOOM! GTS

Table 3.

| SOFTWARE AND APPLICATION | LATEST VERSION | LATEST SOFTWARE FILE | HARDWARE PART NUMBER | OWNER'S MANUAL |
|---|---|---|---|---|
| BOOM! BOX GTS - North America | M23.22.27.00 | swdl_boombox_GTS_DOM.zip | • 76000783<br>• 76000779<br>• 76000786<br>• 76000796 | BOOM! BOX GTS Owner's Manual |
| BOOM! BOX GTS - Europe (HDI) | M23.22.27.00 | swdl_boombox_GTS_HDI.zip | • 76000784<br>• 76000780<br>• 76000787<br>• 76000797 | |
| BOOM! BOX GTS - Rest of World (ROW) | M23.22.27.00 | swdl_boombox_GTS_ROW.zip | • 76000785<br>• 76000781 | |

**Updating the factory installed radio:**

- Download the .ZIP file
- Right click mouse, select "Extract all"
- Click browse and click the USB drive
- Click Extract

**Updating the factory installed radio:**

- Connect USB to radio port on the motorcycle
- Turn on motorcycle
- A screen will pop up, click OK

**Updating the factory installed radio:**

- Wait for the authentication process to AutoStart

**Updating the factory installed radio:**

- With ignition on, Click YES

**Updating the factory installed radio:**

- Wait until the updated is complete
- Radio will restart
- Turn off Motorcycle
- Remove USB from vehicle